



Incoming Inspection Check

29/09/2024 / 90583305 / 385294 / 1499 / Sydney / UE / Battery Electric

Complete

Serial Number

90583305
12 - NH - KMS - LOW LEVEL ORDER
PICKER

Hour Meter Read

1499

Service Job No.

385294

Location

Sydney

Conducted on

30/09/2024 7:52 AM ACST

Conducted By

Thomas Mullins

Truck Category

UE

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4

Wheels/Tyres		
Front Wheels / Tyres		WEAR & TEAR
SLIGHT FLAT SPOT ON ALL WHEELS		
Rear Wheels / Tyres		WEAR & TEAR
Wheel Bearings		OK
Chassis/Structure		
Overhead Guard		N/A
Chassis		OK
Battery Cover		OK
Driver Seat & Fixing		N/A
Panels and Covers (Left & Right)		OK
Accessories (Mirrors, Blue Lights)		WEAR & TEAR
BLUE NOT WORKING		
Windscreen		N/A
Rear Screen		N/A
Arm Rest		N/A
Connection Elements		OK
Drive Unit		
Transmission Operation		OK
Transmission Noise & Leaks		OK
Drive Motor Condition		OK
Brake		

Brake Function & Adjustment	OK
Steering	
Steer Motor Operation/Noise	OK
Steering Cylinder	OK
Steer Axle	OK
Steering Wheel/Controls	OK
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	N/A
Forks & Fork Carriage	OK
Lift Chains Free & Secondary	N/A
Hydraulic Cylinder Free Lift	OK
Hydraulic Cylinders Secondary Light Right & Left	N/A
Hydraulic Hoses Conditions	OK
Reach Carriage & Cylinder	N/A
Sideshift Carriage & Cylinder	N/A
Tilt Function & Cylinders	N/A
Hydraulic System	
Valve Block	N/A
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK
Electric System	
Multi-pilot & Solo-pilot	N/A
Strobe & Working Lights / Alarms	WEAR & TEAR
BLUE LIGHT NOT WORKING	
Drive Display, Console & Instruments	OK
Main Contactor & Connectors	OK

Charger Condition & Operation	OK
Battery	
Battery Condition & Cables	OK
Battery Carriage	OK
Battery Lock System	OK
Additions or Attachments	
Any other related attachments	No
Was any wear & tear identified? ALL WHEELS HAVE SLIGHT FLAT SPOTS	Yes
(Internal) Parts required NA	
Was any damage identified?	No

Media summary



Photo 1



Photo 2



Photo 3



Photo 4