



## **DISCLAIMER: Second-Hand Plant Condition and Safety**

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

### **Important Information**

#### **Safety & Compliance of the Plant**

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed** Condition Report sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

#### **Operational Safety Notice**

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

#### **Operating condition of the plant**

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



## Used Sale Safety & Compliance Check

MHE-000081 / 112946 / Adam Spence / 17/10/2025 /  
Jungheinrich / ETV214

Complete

Flagged items

0

Report ID

MHE-000081

Technician Name

Adam Spence

Conducted on

17/10/2025 9:43 AM AEDT

Branch

Melbourne

Unit Details

Equipment No.

112946

Brand

Jungheinrich

Model

ETV214

Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3




Photo 4

## Observations Summary

### Truck Category

Category 5 - Electric Reach Truck

**Emergency Stop, Horn/Warning device, lights, reverse alarm and flashing lights operational**

Yes

**Foot switch allows operation only when depressed**

Yes

**Seat switch and seat belt operate sequentially (site dependent)**

N/A

**Mast switch operation for travel speed reduction to 3km/h above specified height**

Yes

**Are brakes and park brake functioning correctly?**

Yes

**Are tyre treads within limits and/or free from damage?**

Yes

**Are fork tynes in good condition and within specification?**

No

Customer damage Tynes are bent

**Are mast chains in good condition, within specification and working correctly?**

No

Free lift chains worn beyond limit at 1.75%

**Are all controls inc. lift, tilt & sideshift/auxilliary functions working correctly**

Yes

**Confirm safety systems not bypassed or malfunctioning?**

Yes

## Additional Observations & Actions

### Technician Sign off



Adam Spence  
17/10/2025 11:14 AM AEDT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4