

Coates Hire Pre Divestment Inspection Checklist Portable Buildings, Complexes and Toilet Blocks

6x3 SHEU

196630.

Service Job #

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

*** Copy Data Plate information in this section ***

6x3 SITEU

PRESTIGE

2004

6x3 SYSTEM

2378

MILWAUKEE.

Comments: _____

BUILDING:

Yes ☒ No ☐

☒ Yes ☐ No

11

☒

☒	☐
☒	☐

☒	☐
☐	☐

EXTERNAL:

Yes ☒ **No** ☐

☒ ☐☒ ☐

11

INTERNAL:

Yes ☒ No ☐

☒ ☐

COMPLEXES:

Yes No

EXTERNAL CONDITION OK, CLADDING MAY NEED UPDATING
S AT BASE OF BUILDING + DOOR FRAME, FEW DENT-
MENTED REQUIRES UPDATING. INTERIOR WALLS MARKED-
ING SIGNS OF WATER DAMAGE. FLOOR (CRACKED)
+ MARKED NEEDS REPLACING. ROOF ONLY USUALLY INSPECTED

Job Title: REPAIRMAN
 Hire: 1 MARKED NEEDS REPLACING FOOT ONLY USUALLY INSPECTOR

SHELL ONLY, ELECTRIC CHECKS NOT COMPLETED

Name: A. Curtis

Signature:

Date: 01-07-26

Signed for and on behalf of the Buyer:

Name:

Signature:

Date: