

W/O No	Asset No	Asset Description	Finished Date/Time	Job Type	Description	Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs
					Flat battery not started - 2849hr 6/10/25-test starting fault remove battery for replacement							
01872	M593	CAT CW12 MULTI TYRED ROLLER	7-Oct-2025	Repairs	7/10/25 replace battery 1x battery from xceed \$317.58			4	MNM			317.58
01385	M593	CAT CW12 MULTI TYRED ROLLER	9-Sep-2025	Compliance	MNM Brake Test Due - Perform brake test, complete, scan and submit paperwork. GRV Site Intro.		1	1	MNM			
00123	M593	CAT CW12 MULTI TYRED ROLLER	26-Mar-2025	Compliance	2754 - Site specific introduction 250HR SERVICE (MULTI TYRE ROLLER) Service due at 2750hrs 2754hrs - Service. Adjust scrapers. Measure up door seal. Roughly 5m in total tried to get one from xceed with no luck. New air filter next service. Door seals are damaged. First aid kit missing - replaced with new kit		2	2	GRV			
01259	M593	CAT CW12 MULTI TYRED ROLLER	21-Mar-2025	PM		5	5		GRV			
01033	M593	CAT CW12 MULTI TYRED ROLLER	1-Feb-2025	PM		0.5	0.5		GRV		671.97	
00606	M593	CAT CW12 MULTI TYRED ROLLER	6-Dec-2024	Compliance	GRV Brake Test Due - Perform brake test, complete, scan and submit paperwork.		1	1	GRV			
00446	M593	CAT CW12 MULTI TYRED ROLLER	31-Oct-2024	Repairs	Scraper plate rubbing on wheels/ making noise - repaired		3	3	GRV			
00047	M593	CAT CW12 MULTI TYRED ROLLER	9-Oct-2024	Compliance	GRV Brake Test Due - Perform brake test, complete, scan and submit paperwork.		0.5	0.5	GRV			
00171	M593	CAT CW12 MULTI TYRED ROLLER	4-Oct-2024	Compliance	MNM Brake Test Due - Perform brake test, complete, scan and submit paperwork.		0.5	0.5	MNM			
13119	M593	CAT CW12 MULTI TYRED ROLLER	18-Jul-2024	Compliance	18.07.2024_SC_IH_MWR - Locate machine onsite, perform brake test, complete, subn		0	0	GRV		180	0
13104	M593	CAT CW12 MULTI TYRED ROLLER	26-May-2024	PM	500HR SERVICE (MULTI TYRE ROLLER)Service due at 2500hrs (2472hrs on 25/05)26.05		5.5	5.5	GRV		660	443.711923
13043	M593	CAT CW12 MULTI TYRED ROLLER	11-May-2024	Compliance	COMP - Anglo GRV Plant & Equipment Annual Site Introduction.11.05.2024_MWR_SC		1.5	3	GRV		360	0
13042	M593	CAT CW12 MULTI TYRED ROLLER	11-May-2024	Compliance	COMP - Anglo MNM Plant & Equipment Annual Site Introduction.10.05.2024_MWR_S		0	3	MNM		360	0
12668	M593	CAT CW12 MULTI TYRED ROLLER	27-Mar-2024	Compliance	COMP - Anglo MNM Plant & Equipment Statutory Brake Tests27.03.2024_MWR_SC - F		0	0.75	MNM		90	0
12667	M593	CAT CW12 MULTI TYRED ROLLER	27-Mar-2024	Compliance	COMP - Anglo GRV Plant & Equipment Statutory Brake Tests27.03.2024_MWR_SC - Ph		0.75	0.75	GRV		90	0
12332	M593	CAT CW12 MULTI TYRED ROLLER	23-Feb-2024	PM	250HR SERVICE (MULTI TYRE ROLLER)Service due at 2250hrs (2223hrs on 23/02)23.02		1.5	1.5	GRV		180	264.211534
12174	M593	CAT CW12 MULTI TYRED ROLLER	16-Jan-2024	Compliance	COMP - Anglo GRV Plant & Equipment Statutory Brake Tests.16.01.2024 Brake test co		0	0	GRV		120	0
12173	M593	CAT CW12 MULTI TYRED ROLLER	16-Jan-2024	Compliance	COMP - Anglo MNM Plant & Equipment Statutory Brake Tests.16.01.2024 Brake test c		1	1	MNM		120	0
12165	M593	CAT CW12 MULTI TYRED ROLLER	5-Feb-2024	Repairs	Lever for seat adjustment snapped.MRF7024_M593_GRV_08.01.2023.05.02.2024_Mh		2	2	GRV		240	5.83
12164	M593	CAT CW12 MULTI TYRED ROLLER	15-Jan-2024	Repairs	Hook to hold the wheel scraper snapped.MRF7024_M593_GRV_08.01.2023.15.01.202		2	2	GRV		240	0
12002	M593	CAT CW12 MULTI TYRED ROLLER	10-Jan-2024	Repairs	Noise in AC Fan and struggling to be cool.MRF7012_M593_GRV_30.11.2023.10.01.202		0	0	GRV		480	0
11938	M593	CAT CW12 MULTI TYRED ROLLER	11-May-2024	Repairs	Difficult to keep in a straight line.MRF7008_M593_GRV_21.11.2023.11.05.2024_MWR		0	11	GRV		1320	0
11930	M593	CAT CW12 MULTI TYRED ROLLER	23-Nov-2023	Compliance	COMP - Anglo GRV Plant & Equipment Statutory Brake Tests23.11.2023_MWR_ES - Ci		0	0.5	GRV		60	0
11929	M593	CAT CW12 MULTI TYRED ROLLER	23-Nov-2023	Compliance	COMP - Anglo MNM Plant & Equipment Statutory Brake Tests23.11.2023_MWR_ES - C		1	1	MNM		120	0
11882	M593	CAT CW12 MULTI TYRED ROLLER	26-Nov-2023	Repairs	Coolant Cap leaking. (noted at 2000hr service)26.11.2023_MWR_SP - CHANGED OUT I		0.5	0.5	GRV		60	28.94
11802	M593	CAT CW12 MULTI TYRED ROLLER	11-Nov-2023	PM	2000HR SERVICE (MULTI TYRE ROLLER)2000hr Service Due (1983hrs on 11/11)11.11.2i		5	5	GRV		600	800.705379
11467	M593	CAT CW12 MULTI TYRED ROLLER	19-Sep-2023	External	GRV Brake Test Due.19.09.2023_MWR_SC - Perform brake test, complete, scan and su		0	1	GRV		120	0
11466	M593	CAT CW12 MULTI TYRED ROLLER	19-Sep-2023	External	MNM Brake Test Due.19.09.2023_MWR_SC - Perform brake test, complete, scan and s		0	1	MNM		120	0
11096	M593	CAT CW12 MULTI TYRED ROLLER	27-Jul-2023	Repairs	Filter missing on Spray System, Hastings to supply.27.07.2023_MWR_WA - Fit and con		2	2	Workshop Msh		240	43.9
10987	M593	CAT CW12 MULTI TYRED ROLLER	11-Jul-2023	Compliance	GRV Site Intro.11.07.2023_MWR_SC - Perform Site Intro, compile, complete and scan		0	1	GRV		120	0
10986	M593	CAT CW12 MULTI TYRED ROLLER	11-Jul-2023	Compliance	MNM Site Intro.11.07.2023_MWR_SC - Perform Site Intro, compile, complete and scai		0	2	MNM		240	0
10899	M593	CAT CW12 MULTI TYRED ROLLER	9-Jul-2023	Site Comp	Fitters Compliance Inspection.09.07.2023_MWR_SP - COMPLETED HOSE REGISTER (SI		8.5	8.5	GRV		1020	736.25