

Make: Komatsu Yr: - 2010 Rego Plate: - N/A
 Model: FG35AT-16 Serial Num: 753111-K20080

Maintenance Record - Forklift (F11)

Date	Repair Description	Repaired By	Comments	Invoice #	Cost
16.06.2016	MODIFY MAN CAGE	BELGENNY ENGINEERING		0554	\$264.00
16.07.2016	CARRY OUT SERVICE REPLACE ALL FILTERS AND OILS	ON TRAK EARTHMOVING		00000845	\$964.80
20.11.2016	MAKE DUST SUPPRESSION SPRAY BAR, SUPPLY FITTING FOR DUST SPRAY BAR TO FIT 1000LITRE DRUM	BELGENNY ENGINEERING		0906	\$ 792.00
13.02.2017	MACHINE HOURS 994, CARRIES OUT SERVICE AS REQUIRED. REPLACED CARRIAGE BOLTS	ON TRAK EARTHMOVING REPAIRS PTY LTD		00001175	266.91
18.10.2017	HOURS 1490. CARRY OUT ENGINE SERVICE	ON TRAK EARTHMOVING REPAIRS PTY LTD	1200	00001562	262.15
18.10.2018	GREASE, SERVICE, CHECKOVER	JB EXCAVATIONS		Inv-0034	249.37
19.11.2018	4505HOURS, REPAIR WIRE TO GAS REGULATOR	JB EXCAVATIONS		Inv-0052	132
18.11.2019	FIT NEW BECON	IN HOUSE		n/a	n/a
14.07.2020	FOOT BREAK FIXED	IN HOSUE		n/a	n/a
19.10.2020	BATTERY PACK FOR BATTERY	RJ BATTERIES		17A016284	102.38
5.11.2021	HOURS- 2765, CARRIED OUT 250 HOUR SERVICE -FILTERS CHANGED OIL, AIR AND ENGINE	ON TRAK EARTHMOVING REPAIRS PTY LTD		00003310	297.37
31.01.2022	CARRIED OUT SERVICE, HOURS 3016	ON TRAK EARTHMOVING REPAIRS PTY LTD		00003434	436.18
24.12.21	STRIP AND FIT SOLID TYRES	WEST CITY TYRES		72162	621.5
01.02.2022	SUPPLIED HOSE FITTING TO REPLACE BURST AND WORN HOSES ON FORKLIFT	ON TRAK EARTHMOVING REPAIRS PTY LTD		0003453	1825.18
24.04.2022	REMOVE WHEEL AND AXLE. PRESS OF BRAKE DRUM. STRIP/CLEAN BREAK ASSEMBLY, REPLACE WHEEL CYLINDER ASSEMBLIES. ADJUST, BLEED AND TEST	ON TRAK EARTHMOVING REPAIRS PTY LTD		00003597	1508.73
06.07.2022	TOPED UP OIL LEVELS, DIAGNOSED DIFFERENT FAILURE, DRAINED DIFFERENT OIL WHICH CONTAINED METAL, CHECKED ON CORRECT OILS FOR TRANSMISSION AND DIFFERENTIALS	ON TRAK EARTHMOVING REPAIRS PTY LTD		00003699	\$460
25.07.2022	REPOSITION, RAISE AND BLOCK MACHINE. REMOVE DRIVE SHAFT, PARK BRAKE CBALE, MAST HOSES AND MAST	ON TRAK EARTHMOVING REPAIRS PTY LTD	6 HOURS LABOUR	3717	\$790
14.10.2022	TRAVEL TO SITE SUPPLY FITTINGS AS REQUESTED BY STEFAN	ON TRAK EARTHMOVING REPAIRS PTY LTD		00003834	147.68

Make: Komatsu Yr: - 2010 Rego Plate: - N/A
 Model: FG35AT-16 Serial Num: 753111-K20080

12.10.2022	TRAVEL TO SITE REPAIR REBUILD FRONT AXLE ASSEMBLY FOR INSTALLATION .CLEAN ALL REQUIED PARTS REMOVE BRAKE COOLING PUMP.STRIP, CLEAN AND INSPECT FLUSHES LINES AN FERIL PUMP REPLACE TRANSMISSION MOUNTS AND INSTALLDIFFERENTIAL CONNECT LINES AN DRIVE BELT SHAFT CARRY OUT SERVICE .REPLACE ENGINE TRANSMISSIONS AN HYDRAUILC OILS CLEAN HYDRAULIC TANK AND REPLACE SUCTION SCREEN.REPLACE ALL FILTERS GREASE AN INSTALL WHEELS START AN RUN BLEED BRAKES	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR X33 HOURS	00003823	\$4,195
16.12.2022	INSTALL MAST AN HOSES. INTSALL ROTATOR TEST AND CLEAN AREA	ON TRAK EARTHMOVING	LABOUR X2 HOURS	00003903	\$363.23
31.01.2023	DIAGNOSE AND REPAIR LEAKS ON FORKLIFT	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOURS 7 HOURS	3940	1618.05
09.02.2023	TRAVEL TO SITE DIAGNOSE AND REPLACE BLOWN AND DAMAGED ROTATOR HOSES AS REQUESTED BY STEF	ON TRAK EARHTMOVING REPAIRS PTY LTD	LABOUR 4.5 HOURS	00003985	\$1,261.27
17.02.2023	STRIP DASH AND REMOVE STEERING WHEEL, REMOVE PANNELS AND STEERING	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR 1.5 HOURS	00003985	\$431.82
15.09.2023	CARRY OUT ENGINE SERVICE AS REQUESTED BY STEF	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR 1.5 HOURS, SERVICE CALL, PARTS	00004322	\$346.45
08.11.2023	TRAVEL TO SITE, CAP OFF SIDE SHIFT LINES ON FORKLIFT, AS REQUESTED BY STEF	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR X3 HRS	00004455	\$429.00
03.01.2024	INSPECT BRAKES ISSUE. RAISE AND BLOCK MACHINE. REMOVE WHEELS AND HIBS ETC. INSPECT BRAJE CONDITION. ADJUST AND REASSEMBLE. BLEED BRAKES AND TEST.	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR X2 HOURS, SERVICE CALL	00004526	\$1,132.00
18.01.2024	PARTS- BRAKE MASTER CYCLINDER	ON TRAK EARTHMOVING REPAIRS PTY LTD	SERVICE CALL, LABOUR X4 HRS	00004570	\$682.00
	REMOVE AND REPLACE RADIATOR. REFILL AND TEST				