



ABN 90090840412

## MOTOR BOAT INSURANCE

CLIENT'S NAME:	[REDACTED]
DATE OF INSPECTION:	09 September 2021
SITE:	Presidents Boatshed, Drummoyne NSW
VESSEL DESIGN:	Mariner 38, Stamped 1984
REGO NO:	AH1165N
HIN:	AUWWA-174691AB3 & M388551184
GENERAL DESCRIPTION:	Flybridge Cruiser
CONSTRUCTION:	Composite GRP



Phone: 0418 442 515

Email: [gavin@boatsurveying.com.au](mailto:gavin@boatsurveying.com.au)

Website: <http://www.boatsurveying.com.au/>

## **HULL**

TOPSIDES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
BOTTOMS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
ANTIFOULING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	New application
HULL AND DECK JOIN:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
KEEL AND FIXINGS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No damage
RUBBING STRIP:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured with wear and tear
BULKHEADS AND BONDINGS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
BOARDING OR SWIM PLATFORM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured with wear and tear
ENGINE BEDS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound
CHINES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No damage noted
BOARDING PLATFORM SUPPORT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and undamaged
TRANSOM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
STEM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear



## **SEACOCKS AND THROUGH HULL FITTINGS:**

TOILET INTAKE FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
TOILET OUTLET FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
THROUGH HULL TRANSDUCERS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured
SINK OUTLET FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
SINK OUTLET AFT:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
SINK OUTLET GALLEY :	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
ENGINE INTAKE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
EXHAUST OUTLET:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
DECK WASH INTAKE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
WATER MAKER INTAKE	<input type="checkbox"/>	<input type="checkbox"/>	
GENERATOR INTAKE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
GENERATOR EXHAUST	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational



### **CATHODIC PROTECTION**

	Accept	Non Accept	Comments:
HULL ANODES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Maddox fitted
SHAFT ANODES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
TRIM TAB ANODES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	



### **DECK AND TOP MOLDINGS**

CABIN SIDES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
CABIN TOP:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
DECK STRUCTURE:	<input type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
FLYBRIDGE STRUCTURE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
BOW RAIL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured with wear and tear
BULWARKS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
GRAB RAILS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured
HATCHES AND PORTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Weathertight
WINDOWS AND SCREENS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Weathertight
ANCHOR WINCH MOUNTINGS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
ANCHOR:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable
ANCHOR CHAIN AND WARP:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable
BOW FITTINGS AND ROLLERS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured with wear and tear
CLEATS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured
HARD TOP	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structurally sound with wear and tear
COMPANIONWAY DOORS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured, weathertight and lockable



***ELECTRICAL SYSTEM: 12V OR 24V***

BATTERIES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
DISTRIBUTION PANEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SALLOON LIGHTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
FWD CABIN LIGHTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
GALLEY LIGHTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
HEAD LIGHTS FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
NAV LIGHTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
STEERING LIGHT:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ANCHOR LIGHT:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
COCKPIT LIGHTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
FANS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ENGINE BLOWERS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
STEREO:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ANCHOR WINDLASS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SALOON FRIDGE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>





AUTO HELM:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
VHF RADIO:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
TOILET FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
SHOWER SUMP FWD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
WATER PRESSURE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
DECK WASH:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
COCKPIT/TRANSOM SHOWER:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
BILGE PUMPS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	All tested operational
HORN	<input checked="" type="checkbox"/>	<input type="checkbox"/>	



### ***ELECTRICAL SYSTEM: 240V***

POWER POINTS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
BATTERY CHARGER:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
HOT WATER SYSTEM:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

FRIDGE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SHORE POWER LEAD:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
RCD FITTED:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
DISTRIBUTION PANEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>



### ***MECHANICAL: PORT ENGINE***

MAKE AND MODEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cummins 555 - 270 hp
OIL CONDITION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Last service March 2021



### ***MECHANICAL: STB ENGINE***

MAKE AND MODEL:	<input type="checkbox"/>	<input type="checkbox"/>	Cummins 555 270 hp
SERIAL NO:	<input type="checkbox"/>	<input type="checkbox"/>	
HRS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2270
OIL CONDITION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Last service March 2021





### ***MECHANICAL: GENERATOR 1***

MAKE AND MODEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Onan 5MDKD
HRS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	810
OIL CONDITION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Last service June 2020



### ***STEERING SYSTEM***

HYDRAULIC RAM:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational
WHEEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured
RUDDERS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No damage
RUDDER GLANDS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable
HYDRAULIC LINES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No leaks
AUTO PILOT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Operational
RUDDER ANGLE INDICATOR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Accurate



### ***RUNNING GEAR***

PROPELLORS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No damage
PROPELLOR SHAFTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No damage
STERN GLANDS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Service at 2022 out of water period
SKEG & BEARINGS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No movement
RUDDER BEARINGS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable
TRIM TABS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Secured and operational , cover missing off hydualic hose penetration



### ***PLUMBING AND TANKS***

	Accept	Non Accept	Comments:
FUEL:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No leaks noted
WATER:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No leaks noted
HOSES AND CLAMPS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable
BILGE PUMPS AND SYSTEM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	All tested operational

### ***FIT OUT AND FURNISHINGS:***

SEATING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
HEAD LINER:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
HULL LINING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
DOORS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
FLOOR BOARDS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
TIMBER TRIMS ETC:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear





### ***COVERS AND CLEARS***

AWNING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
FLYBRIDGE CLEARS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear
SCREEN COVERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Acceptable with wear and tear







## ***RECOMMENDATIONS***

1. Schedule Stern Gland service at 2022 OOW Period
2. Fit shroud cover to hydraulic hose penetration on transom



## REMARKS

The Hull has been built to current professional standards and has been well maintained. The defects aforementioned should be attended to at the soonest opportunity. The above vessel is structurally sound and in my opinion is an insurable item. This report reflects and expresses the opinion of Slipstream Marine Enterprises Pty Ltd. All reasonable attempts to detect any defects present, however, there may exist hidden or latent defects, or those that cannot be discovered without interfering with the vessels structure. This report is given without prejudice and is for the exclusive use of Haidar Alshanoon and no responsibility will be accepted for any other party without the written consent of the undersigned.

G J CLARK

SHIPWRIGHT/BOATBUILDER

AMSA ID: 129576

MARINE SURVEYOR

DATE: 09 September 2021



Phone: 0418 442 515

Email: [gavin@boatsurveying.com.au](mailto:gavin@boatsurveying.com.au)

Website: <http://www.boatsurveying.com.au/>