



Vehicle History Summary



Fleet #	LE29
Registration	44816E
Make	Kobelco
Model	SK500LC
VIN / Chassis #	YS12-03525
Build Date	2014

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer Notes	Repairer
R-288	28/01/2025	0	14051	0	front window	replaced	
R-287	14/01/2025	0	14030	0	dpf filter	replaced dpf filer	Lentro Earthworks
R-266	12/11/2024	0	13840	0	undercarriage	retighten	
S-486	15/10/2024	0	13696		A - 500hr		
S-396	10/01/2024	0	13232		D - 5000hr	just to get hr up to date	
S-200	10/01/2024	0	13232		A - 250hr	Right slew motor minor oil leak Replaced O rings on slew motor	Lentro Earthworks
S-124	20/10/2023	0	13950		B - 500hr	Oil leak top ram z xx	Lentro Earthworks
I-53	16/10/2023			0	Plant Risk Assessment		
S-100	30/07/2022	0	11614		B - 500hr		Internal Workshop
S-77	17/02/2022	0	11279		A - 250hr		Internal Workshop
S-60	29/11/2021	0	11014		C - 1000hr		
R-78	06/10/2021	0	0	0	Hydraulics lerak		ENZED Service Centre Canberra
R-76	23/09/2021	0	0	0	Cab		Internal Workshop
S-44	08/09/2021	0	10771		A - 250hr		Lentro Earthworks
R-62	05/08/2021	0	0	0	top up hyd oil	toped up oil	Internal Workshop
S-32	26/07/2021	0	10610		B - 500hr	Hydraulic Leak - Suction hose	Internal Workshop
R-16	18/05/2021		10282	0	Battery	Replace with new EE stop	Internal Workshop
R-5	13/05/2021	0	10274	0	undercarriage	replace with new chains & Sprockets	Internal Workshop
S-4	13/05/2021	0	10274		A - 250hr	Service 250hr	Internal Workshop

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer Notes	Repairer
I-54	01/02/2021			0	Plant Risk Assessment		

Signed: _____

Name: _____

Date: _____