

**RGM Maintenance Pty Ltd**

351 Main Myrtle town Road, Pinkenba, Queensland 4008

Phone: 07 3260 1224

Fax: 07 3260 1243

Email: pnk@rgmmaintenance.com.au

Website: www.rgmmaintenance.com.au

ABN: 18 100 509 484

ACN: 100 509 484



\*\*\* DOCUMENT COPY \*\*\*

**Invoice To:**

Internal Used

Stock No. 700369

**Deliver To:****SERVICE TAX INVOICE**

**Document No.:** 1221755  
**Document Date:** 26/07/2022  
**Repair Order No.:** 328888  
**Rego No.:**  
**Make/Model:** /O VOLVO FH600 GLOBETROTTER  
**Vehicle ID No.:** YV5RP80D4GD204235  
**Odometer:**  
**Hours:**  
**Fuel burn:**  
**Delivery Date:** 04/05/2022  
**Customer ABN:**  
**Fleet No.:**  
**P/Order No.:**  
**Pre Auth id.:**  
**Page:** 1 of 4

## CARRY OUT INSPECTION AND REPAIRS

**\$8,535.00**

Part Number	Part Description	Quantity	Nett Value	Total Cost
SSA100	ARCH SPRAY SKIRT	2.00	28.98	57.96
MB-QBW K026427	BRAKE VALVE	1.00	643.06	643.06
20734773	ADAPTER	2.00	31.66	63.32
A06-69847-000	LAMP	1.00	545.99	545.99
21957045	SWITCH	1.00	297.72	297.72
22332600	LAMP FOG	1.00	351.88	351.88
4603008	CORE AIR DRYER	1.00	420.00	420.00
82446592	INSERT	1.00	7.86	7.86
21297918	LAMP LH	1.00	474.34	474.34
85023466	AIR DRIER, EXCH	1.00	2,052.91	2,052.91
84814288	INTERIOR LAMP	1.00	126.86	126.86
100-505	LONG TAIL	1.00	152.34	152.34
101AUSKIT	KIT REBUILD	1.00	427.77	427.77
QPOL 34102PF	MIRROR SWITCH	1.00	79.19	79.19
MB205	RADIO MIC MOUNT	2.00	13.25	26.50
22629273	SWITCH	1.00	289.61	289.61
22629276	SWITCH STEERING	1.00	128.25	128.25
23397886	WIRES	1.00	55.07	55.07
84429874	WIND DEFLECTOR KIT	1.00	365.93	365.93
CLIP.HS1	H SPRING CLIP	12.00	0.88	10.56
82884080	AIR DUCT	1.00	42.26	42.26
82380308	STEERING WHEEL	1.00	822.76	822.76
RBL5320C	BAR LIGHT LED	1.00	369.00	369.00
20736230	SEAL STRIP	1.00	225.46	225.46
TT5571	TURNTABLE	1.00	1,989.38	1,989.38
991083	SWIVEL	2.00	36.10	72.20
22239228	HEADLAMP	2.00	845.38	1,690.76
90862BLNA	MDL8 LED GREY L/PLATE LAMP	2.00	20.49	40.98
M9T66371AMA	24V 12TH STARTER	1.00	703.54	703.54

**RGM Maintenance Pty Ltd**  
 351 Main Myrtle town Road, Pinkenba, Queensland 4008  
 Phone: 07 3260 1224  
 Fax: 07 3260 1243  
 Email: pnk@rgmmaintenance.com.au  
 Website: www.rgmmaintenance.com.au  
 ABN: 18 100 509 484  
 ACN: 100 509 484



\*\*\* DOCUMENT COPY \*\*\*

**Invoice To:**  
 Internal Used  
 Stock No. 700369

**Deliver To:**

## SERVICE TAX INVOICE

**Document No.:** 1221755  
**Document Date:** 26/07/2022  
**Repair Order No.:** 328888  
**Rego No.:**  
**Make/Model:** /O VOLVO FH600 GLOBETROTTER  
**Vehicle ID No.:** YV5RP80D4GD204235  
**Odometer:**  
**Hours:**  
**Fuel burn:**  
**Delivery Date:** 04/05/2022  
**Customer ABN:**  
**Fleet No.:**  
**P/Order No.:**  
**Pre Auth id.:**  
**Page:** 2 of 4

3944785	AIR FILTER - ADBLUE	2.00	83.06	166.12
BUY IN	"SPECIAL BUY IN"	34.00	119.84	4,074.50
<i>Comments: P/N NR84036BL</i>				
<i>P/N GP-921-08 ADAPTOR</i>				
<i>GP-941-08 COUPLING</i>				
<i>P/N CA2561 SUZI COIL</i>				
<i>P/N CA93-23 ADAPTOR</i>				
<i>P/N CA93-87 COUPLING</i>				
<i>P/N 130.0014 REAR MARKERS</i>				
<i>P/N 60.0102 LOOP KIT</i>				
<i>p/n SK3106007 TOP PLATE</i>				
<i>SK1259 BUSH</i>				
<i>SK210525 RUBBER</i>				
<i>P/N SS11SINCNG CURVED EDGE</i>				
<i>P/N 82485683 WIPER BLADE KIT</i>				
<i>P/N 23515346</i>				
<i>P/N 23515329 CAB FILTER</i>				
<i>P/M 21392187 FOOT BOARD</i>				
<i>P/N 21874450 PANEL H/LAMP</i>				
<i>P/N 21634891 SPRING</i>				
<i>P/N 23111320 SHOCK ABSORBER</i>				
<i>P/N 21544777 SPRING</i>				
<i>P/N 21739593 SHOCK ABSORBER</i>				
<i>P/N A0000903651 FUEL PRO</i>				
22343365	CABLE HARNESS	1.00	1,580.86	1,580.86
FLC A18-67226-002	REG ASY ELEC WDO DUAL LH	1.00	560.99	560.99
MB-QFLC FLSK96018	MATT CST112 34"69X190	1.00	514.01	514.01
QFLC 03-36867-010	FILTER ELEMENT-AIR 8X25	1.00	536.99	536.99
QFLC A06-36841-000	LAMP-VALANCE LED W/S	4.00	106.79	427.16
SHEVOLFMHV4T499CHA	VOLVO T499 FM VERS	1.00	540.06	540.06
SHEVOLISRIFMT499CHA	VOLVO ISRI FM VERS	1.00	540.06	540.06
MB-QFLC 03-36867-010	FILTER AIR	1.00	469.22	469.22
JSK37WP	TURNABLE TOP 37CZ	1.00	3,231.21	3,231.21

**Parts Totals: 94.00 \$25,174.64**

**RGM Maintenance Pty Ltd**  
 351 Main Myrtle town Road, Pinkenba, Queensland 4008  
 Phone: 07 3260 1224  
 Fax: 07 3260 1243  
 Email: pnk@rgmmaintenance.com.au  
 Website: www.rgmmaintenance.com.au  
 ABN: 18 100 509 484  
 ACN: 100 509 484



\*\*\* DOCUMENT COPY \*\*\*

**Invoice To:**  
 Internal Used  
 Stock No. 700369

**Deliver To:**

**SERVICE TAX INVOICE**

**Document No.:** 1221755  
**Document Date:** 26/07/2022  
**Repair Order No.:** 328888  
**Rego No.:**  
**Make/Model:** /O VOLVO FH600 GLOBETROTTER  
**Vehicle ID No.:** YV5RP80D4GD204235  
**Odometer:**  
**Hours:**  
**Fuel burn:**  
**Delivery Date:** 04/05/2022  
**Customer ABN:**  
**Fleet No.:**  
**P/Order No.:**  
**Pre Auth id.:**  
**Page:** 3 of 4

SUBLET REPAIR **\$1,352.00**  
 SUPPLY AND FIT NEW TYRES

SUBLET REPAIR **\$8,810.57**  
 SUPPLY AND FIT NEW WINDSCREEN

SUBLET REPAIR  
 WORK CARRIED OUT BY PENSKE  
 REPAIR FAULT CODES  
 REMOVE AND REPAIR FUEL INJECTORS  
 SUBLET REPAIR  
 ACID WASH VEHICLE

Windscreen

Fittings

Part Number	Part Description	Quantity	Nett Value	Total Cost
000 491 09 30	HEAT SHIELD	1.00	91.16	91.16
451490422B	ELBOW NIPPLE	1.00	26.50	26.50
HTSSF586Z	5/8 X 6 G8 ZP	1.00	11.21	11.21
TE1512BL	RING TERMINAL	1.00	3.52	3.52
993859	ELBOW NIPPLE	1.00	25.90	25.90
991084	SWIVEL	1.00	40.22	40.22
991080	NIPPLE	1.00	25.24	25.24
86AAM	LED AMBER	3.00	24.30	72.90
<b>Parts Totals:</b>		<b>10.00</b>		<b>\$296.65</b>

SUBLET REPAIR **\$1,794.34**  
 VOLVO CALL OUT TO DIAGNOSE FAULTY STARTER  
 SUBLET REPAIR  
 TRACE AND REPAIR WIRING FAULT IN LIGHT BAR AND DRIVER ASSIST MODULE

**RGM Maintenance Pty Ltd**

351 Main Myrtletown Road, Pinkenba, Queensland 4008

Phone: 07 3260 1224

Fax: 07 3260 1243

Email: [pnk@rgmmaintenance.com.au](mailto:pnk@rgmmaintenance.com.au)Website: [www.rgmmaintenance.com.au](http://www.rgmmaintenance.com.au)

ABN: 18 100 509 484

ACN: 100 509 484

**\*\*\* DOCUMENT COPY \*\*\*****Invoice To:**

Internal Used

Stock No. 700369

**Deliver To:****SERVICE TAX INVOICE**

<b>Document No.:</b>	<b>1221755</b>
Document Date:	26/07/2022
Repair Order No.:	328888
Rego No.:	
Make/Model:	/O VOLVO FH600 GLOBETROTTER
Vehicle ID No.:	YV5RP80D4GD204235
Odometer:	
Hours:	
Fuel burn:	
Delivery Date:	04/05/2022
Customer ABN:	
Fleet No.:	
P/Order No.:	
Pre Auth id.:	
Page:	4 of 4

REPLACE REAR WINDOW P  
VOLVO REPAIR FAULT CODES P

Advisor: Justine Weldon

<b>Sub Total for All:</b>	\$45,963.20
<b>Rounding:</b>	\$0.00
<b>GST:</b>	\$0.00
<b>Total:</b>	\$45,963.20

For full Terms and Conditions, please see the details on our website.

**Bank Account Details for Direct Payments:**

BSB: 084742 Account No.: 590037718 Account Name: RGM Maintenance