

VEHICLE SUMMARY



VENDOR STOCK & ITEM #: 51080-1	
Make:	MITSUBISHI
Model:	CHALLENGER
Model year/compliance:	FEB 2001
4WD:	4X4
Body Type	WAGON
Build date:	2001
Engine size:	V6 PETROL
Transmission:	5SP MANUAL
Odometer:	239,069
Rego #:	UNREGISTERED
Interior Colour:	GREY
Exterior colour:	RED
VIN/Chassis #:	JMF0NK9601P000583
Engine #:	NA
Keys:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Spare Keys:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Remote Locking:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Owners Manual:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Service History:	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Partial <input type="checkbox"/> None
<u>DAMAGE / ADDITIONAL COMMENTS:</u>	
Minor dents and scratches	
<u>GENERAL CONDITION</u>	
<i>Seats & Upholstery</i>	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
<i>Floors</i>	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
<i>Controls & dash</i>	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
<i>Paint</i>	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
<u>ESTIMATED AVERAGE FOR VEHICLE TYRE WEAR - (GUIDE ONLY, MAY VARY)</u>	
<input type="checkbox"/> Need replacing <input checked="" type="checkbox"/> 50% <input type="checkbox"/> 75%+	
<u>EXTRAS / OPTIONS:</u>	
Air Conditioning <input checked="" type="checkbox"/>	Power Steering <input checked="" type="checkbox"/>
Power Windows <input checked="" type="checkbox"/>	Cruise Control <input checked="" type="checkbox"/>
SRS Airbags <input checked="" type="checkbox"/>	Climate Control <input type="checkbox"/>
CD Player <input type="checkbox"/>	
<u>NON-STANDARD ACCESSORIES:</u>	
NUDGEBAR	ROOFRACKS
DVD (ROOF MOUNT)	
NB: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report. The report is intended as a guide only and full inspection is highly recommended.	