



View Plant and Equipment

Fri Mar 19 2021 08:27 AM

View Plant and Equipment

[Perform Maintenance](#)

[Upload Document](#)

[Generate PDF](#)

[Back](#)

Machine Name: Caterpillar D8T Dozer P40

Site: STILLER S Pty Ltd

Activity: Dozer Operation

Asset Number: P40

Serial Number: N/A

Model Number: N/A

Machine Use: N/A

Qualifications required: Construction Card,Dozer Licence,Dozer VOC

Training required: Dozer SWMS

Qualified Employees: [Linden Stiller](#)

Plant Item Cost: N/A

Purchase Date: 01-12-2018

Place Of Purchase: N/A

Date Of Sale/Disposal: N/A

Sale Price (if applicable): N/A

Buyer/Place Of Disposal: N/A

Next Maintenance Date: N/A

Maintenance Person: N/A

Email address: N/A

Review Date: N/A

Future Maintenance Schedule: N/A

Responsible Person:

Image:

[Print QR Code](#)



62809 ACT

Dozer Operation

Common QR Codes links

Incident Form

Hazard Form

Selected Qualifications for Plant

Construction Card

Dozer Licence

Dozer VOC

Selected General Induction and Training Requirements

Dozer SWMS

Email Ids for Expired Review Date Alert:

Quick Links:

View Hazards associated with this Machine

View Incidents associated with this Machine

View maintenance items associated with this Machine

[Show Document\(s\)](#)

[Show Log](#)

[Show Maintenance](#)

[Show Checklist\(s\)](#)

[Compliance\(s\)](#)

[Procedure\(s\)](#)

[Induction Log](#)

Details	Date	Completed By	Additional Notes	Attachment(s)
13 500hr service, all oils and filters, new hose on steering motor, new cutting edges, general check over and grease	20-02-2019	Linden Stiller		N/A
13750hr service	02-04-2020	Linden Stiller	engine oil and filters, fuel filters, air cleaner, grease and inspect	N/A
13850hr LH final drive was running hot, found some metal on drain plug, removed from machine, stripped, inspected, replaced all bearings, shims and seals. reassembled and fitted back to machine, runs fine now	24-07-2020	Linden Stiller		N/A
13500hr purchased machine with rebuilt transmittion, torque converter and 1 final drive at 13000hr from flamstead equipment toowomba	20-02-2019	Linden Stiller		N/A
13988hr replace engine oil/filter, fuel filters, air filter, grease anc check over,	04-	Linden		N/A

replace o ring on hose under seat as it was leaking onto belly guards	03-2021	Stiller		
Details	Date	Completed By	Additional Notes	Attachment(s)

[Edit](#) [Cancel](#)