

| | | | | | | | | | | | | | | |
|--------------------------|---|--|---|---------------|---------------------|----------------------|--|-------------------|-----------------|--------------|------------------------|------|------|------|
| AMS STATE | NSW | VENDOR # | | ITEM # | | KEY # | | | | | | | | |
| LOCATION | Rear of 5 Holbeche Road (entry via Prima Place), Arndell Park | | | YARD LOCATION | | | | | | | | | | |
| MAKE | Unsure. | | MODEL | Unsure. | | VARIANT | Unsure. | | | | | | | |
| DRIVE TYPE | FWD | RWD | AWD | 4WD | # SEATS | 1 Seater | | | | | | | | |
| BODY TYPE | Bus | Cab Chassis | Cabriolet | Convertible | Coupe | Dual Cab Chassis | Dual Cab Ute | Extra Cab | | | | | | |
| | Hatchback | People Mover | Sedan | Service Body | SUV | Troop Carrier | Ute | Van | | | | | | |
| | Wagon | motorbike. | | | | | | | | | | | | |
| BUILD | M | / | | | | Unable to locate | | | | | | | | |
| COMPLIANCE | M | / | | | | Unable to locate | | | | | | | | |
| TRANSMISSION | Auto | Clutchless | CVT | DSG | Dual Clutch | Manual | Manual 5sp | Manual 6sp | Sports Auto | | | | | |
| # CYLINDERS | 3 | 4 | 5 | 6 | 8 | 10 | 12 | Rotary | ENGINE CAPACITY | Litres | | | | |
| FUEL TYPE | Diesel | | Dual (LPG/Diesel) | | Dual (LPG & Petrol) | | Electric | | Hybrid | | | | | |
| | LPG | | Petrol | | Turbo Diesel | | Turbo Petrol | | | | | | | |
| REGO | | | | STATE | | | | | | | | | | |
| REGO STATUS | Sold Unregistered, Without Plates | | | | | EXPIRY | Applicable to NSW Drivers Licence Holders Only | | | | | | | |
| ODOMETER | | | | km / miles | | Damaged | | Couldn't Read | | | | | | |
| EXTERIOR COLOUR | Black | | | | INTERIOR COLOUR | Black. | | | | | | | | |
| VIN (must be 17 digits) | | | | | | | | | | | | | | |
| ENGINE NO. | | | | | | | | | | | | | | |
| CONDITION & FEATURES | KEY | Y | N | | | | | OWNERS MANUAL | Y | N | | | | |
| | SERVICE HISTORY | None | | Partial | Good | Full | | ENGINE TURNS OVER | Y | N | | | | |
| | SEATS & UPHOLSTERY | | Good | Fair | Poor | CONTROLS & DASH | | Good | Fair | Poor | PAINT | Good | Fair | Poor |
| | ABS Brakes | Airbag - Front | Airbags - Side Impact 1 st Row | | Air Conditioning | Alloy Wheels | | Bull Bar | | CD Player | | | | |
| | Cruise Control | Driving Lights | DVD Player | | Electric Seats | Heated Seats | | Ladder Racks | | Leather Trim | | | | |
| | Multi-Function Steering Wheel | NSW E-Safety Check (Pink Slip) - Applies to NSW Drivers Licence Holders Only | | Nudge Bar | | Park Assist | Power Steering | | Power Windows | | Remote Central Locking | | | |
| | Reverse Camera | Roof Racks | | ROPS | | Satellite Navigation | Side Steps | | Snorkel | | Spot Lights | | | |
| | Sunroof | Tow Bar | | UHF | | | | | | | | | | |
| MARKS/SCRATCHES LOCATION | Normal wear & tear. | | | | | | | | | | | | | |
| DENTS LOCATION | none. | | | | | | | | | | | | | |
| OTHER NOTES | XXXXXXXXXXXX CHASSIS NUMBER: HE04EB111054. | | | | | | | | | | | | | |
| FREIGHT CODE | 2919 | | | | START PRICE | \$9 | | | | | | | | |

Date Processed: _____

Yard Initials: _____

QC Initials: _____