

Chassis: WDD 205348 2F 580785

Current advice for the vehicle:

none





Outstanding KDM:

none

ESKULAB decisions:

none

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	10.02.2022				Service major - LL - BZ	k149744	AU P	30209	75572	km			
	09.07.2020				Service minor - regelm. Wartung	k127539	AU P	30023	46343	km			
	12.08.2019				Service major - regelm. Wartung	k114155	AU P	30209	30978	km			
	08.06.2018				Service minor - regelm. Wartung	C152364	AU P	30023	13956	km			